

Oil Field Environmental Incident Summary

Incident: 20160521140845 **Date/Time of Notice:** 05/21/2016 14:08

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: FEDERAL 33-1

Field Name: CHARLSON

Well File #: 5727

Date Incident: 5/19/2016

Time Incident: 14:46

Facility ID Number:

County: MCKENZIE

Twp: 154

Rng: 95

Sec: 33

Qtr:

Location Description:

Submitted By: Shawn Dahl

Received By:

Contact Person: Shawn Dahl
2732 Hwy 85 N
Alexander, ND 58831

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

50' by 100' burned area.

Potential Environmental Impacts:

none

Action Taken or Planned:

the fire was put out. the treater is going to be fixed.

Wastes Disposal Location: the oil was burned by the fire. impacted soil will be taken to an approved disposal facility.

Agencies Involved:

Updates

Date: 5/23/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on constructed well site according to the report. NDIC retains oversight.